SITE survey. APP

SITE SURVEY REPORT

Container Inspection

Prepared for	Harbour Logistics Ltd
Date	10 Oct 2026
Site	Harbour Logistics
Prepared by	S. Okoro

FORM

Container Inspection

1. Container

Project	Harbour Logistics: export container check before loading (completed example)
Client	Harbour Logistics Ltd
Site	Felixstowe depot
Site address	Dock Road, Felixstowe
Inspection date	10 Oct 2026
Inspector	S. Okoro
When	Before loading
Container or trailer number	HBLU 482913 9
Type	40 ft high cube
Safety approval plate fitted, with in-date examination details?	Yes

> The US CTPAT minimum security criteria require a seven-point inspection of empty containers before loading: front wall, left side, right side, floor, ceiling or roof, inside and outside doors including the locks, and outside and undercarriage. Refrigerated containers add an eighth point, the fan housing. The checks look for changes made to hide contraband, and for visible pests.

2. Seven-point check

Undercarriage and outside	OK
Doors, inside and outside (locks, hinges, bolts)	OK
Right side	OK
Left side	OK
Front wall	OK
Ceiling and roof	OK
Floor (inside)	Defect
What is wrong?	Shallow gouge in the floorboards by the doors, not through; no light showing. Accepted for this load.

Clean and fit for the load	Dry, Clean, No odour, No pests, No holes or light coming in
Points OK	6
Points with a defect	1

Photos (doors, inside, any defects)



3. Result

Result	Accepted
Seal number applied or checked	HL 0099812
Seal checked: number matches the documents, and it does not pull or twist loose?	Yes
Inspector name	S. Okoro

Inspector signature



Driver name	R. Bell

Driver signature

